

CITY OF SPRINGFIELD

Public Works Department

→ Surveillance Enforcement and Billing
Sewer Maintenance
Sanitary Landfill

1216 W. Nichols
Springfield, MO 65802

PHONE: 417/864-1924

FAX: 417/864-1918



DATE: 8/26/92 FAX #: 895-6954

TO: Mo. DNR - SRO

FROM: R. LYMAN - City of SGF.

MESSAGE: RE: "MILK" SPILL.

PAGES TO FOLLOW: 2

800 W. Tampa

City of Springfield
Water Pollution Control Section
Pollution Complaint/Report Form

Date 8/26/92

Report From: ☐ Citizen
☐ Fire Dept.
☐ Public Information Office
☐ Health Department
☒ Other POLICE DEPARTMENT

Received By: R. LYMAN
Referred To: MO DNR
Date of Incident: 8/25/92

Complainant Information: Name POLICE DEPT.
Address 321 E. CHESTNUT EXP.
Phone 864-1700
Directions (if needed): _____

Responsible Party Information: Name MID-AMERICA DAIRMEN
Address 800 W. TAMPA
Phone 865-9641

Possible contamination of: ☐ soil ☐ groundwater
☒ surface water what body? JORDAN CR.
☐ other _____

Other pertinent information: _____

Who to contact: 895 FAX 895-6954

<input checked="" type="checkbox"/> DNR 417- 837 -6950	<input type="checkbox"/> Health Dept.
<input type="checkbox"/> DNR 314-634-2436	<input type="checkbox"/> Sewer Maintenance
<input type="checkbox"/> EPA 913-236-3778	<input type="checkbox"/> Sewer Construction
<input type="checkbox"/> Fire Dept. 864-1719	<input type="checkbox"/> Chemtrec 1-800-424-9300
<input type="checkbox"/> Police Dept. 864-1719	<input type="checkbox"/> DOT
<input type="checkbox"/> Bob Schaefer	<input type="checkbox"/> NRC 1-800-424-8802
<input type="checkbox"/> CU 831-8320	<input type="checkbox"/> Other _____
<input type="checkbox"/> Street Dept.	


Details of incident: I RECEIVED A CALL AT HOME AT 7:30 P.M.
8/25/92 THAT JORDAN CREEK WAS "BLUE" IN COLOR.
I ARRIVED AT JORDAN CREEK JUST WEST OF THE GRANT
STREET VIADUCT WHERE THE "DOUBLE BOX" STORM SEWER
COMES FROM THE NORTH. I WENT TO THE UPSTREAM
END AND OBSERVED A SLIGHTLY WHITE OR "MILKY" DISCHARGE
COMING INTO THE BOX FROM THE WEST ON WALL ST. EAST
OF MISSOURI AVE. MID-AM HAS THE ONLY DISCHARGE KNOWN.

Action needed: REFER TO D.N.R. AND SEE WHAT CAN
BE DONE TO DETERMINE THE CAUSE OF THESE
EPISODES. THERE HAVE BEEN 3 OR 4 SIMILAR
OCCURRENCES IN THE LAST 18 TO 24 MONTHS

Randy Lyman
8/26/92 - 7:45 A.M.

(over) ADDRESS 800 W. TAMPA

800 W. Tampa



800 W. Tampa

CITY OF SPRINGFIELD
INTER-OFFICE MEMORANDUM

ATTENTION OF _____ FILE _____

DATE _____ April 8, 1982 _____

DEPARTMENT _____

On Monday, April 5, 1982, at 9:35 A.M. Larry Boyd of Mid-America Dairymen, Inc. reported that there had been a stoppage in their sewer line. During the clean-out of the line a little milky water was spilled in the street.

Karen Chandler

Karen Chandler
Water Pollution Control Inspector II
Surveillance & Enforcement

800 W. TAMPA SIGNED _____

APR 27 1981

Joyce: You need to record receipt of payment from Mid-America Dairymen, Inc., for milk spill cleanup on March 31, 1981.

Check in the amount of \$683.88 (amount billed) received 4-24-81, Check No. 4407104.

Charlene

800 W. TOMPA

~~2533 N. CONCEPT~~

April 9, 1981

Mr. Larry Boyd
Mid-America Dairymen, Inc.
P.O. Box 1837, S.S. Station
Springfield, Missouri 65805

Dear Mr. Boyd:

Please be advised that on March 31, 1981 at approximately 11:00 A.M., personnel from the City of Springfield Public Works Department, responded to a spill of milk within the corporate limits of the City. The spillage was due to the pumping out of the receiving area into the storm sewer.

The ordinances of the City provide for recovery of the costs involved in the abatement of a violation under emergency conditions. Payment of those costs should be made to the Director of Finance, City of Springfield, Missouri and sent to:

City Hall
830 Boonville, Room 210
Springfield, Missouri 65802
Attention: Mr. Robert R. Schaefer, P.E.

Attached to this letter, please find a detailed explanation of the costs involved. If you have any questions, please feel free to call 417-864-1925.

Yours truly,

Karen A. Chandler
Water Pollution Control Inspector II
Surveillance and Enforcement

KAC:js
Attachment

cc: Mr. Robert R. Schaefer, P.E., Superintendent of Sanitary Services
Director of Finance
Mr. John R. Nixon, P.E., Regional Administrator, Department of Natural Resources

800 W. TAMPA

Re: Mid-America Dairymen, Inc.

Personnel Costs

March 31, 1981

<u>Personnel</u>	<u>Burden Rate</u>	<u>Total Hours</u>	<u>Cost</u>
Cole	17.95	1.5	\$ 26.93
Lyman	13.68	5	68.40
Pabst	13.68	5	68.40
Corson	13.68	5	68.40
Chandler	10.22	5	51.10
Short	11.43	5	57.15
Total Personnel Cost			<u>\$340.38</u>

Vehicle Costs

March 31, 1981

<u>Vehicle</u>	<u>Hourly Rate</u>	<u>Total Hours</u>	<u>Cost</u>
T2-47 (dumptruck)	15.00	5	\$ 75.00
P2-22 (4 WD)	2.85	5	14.25
P2-44 (4 WD)	2.85	5	14.25
P2-15 (4 WD)	2.85	5	14.25
P2-7 (van)	2.40	5	12.00
Total Vehicle Cost			<u>\$129.75</u>

Equipment Costs

March 31, 1981

<u>Equipment</u>	<u>Hourly Rate</u>	<u>Total Hours</u>	<u>Cost</u>
NP-59 (compressor 1R)	14.20	5	\$ 71.00
NP-303 (electric pump)	3.15	5	15.75
NP-059 (air pump-GD)	1.65	5	8.25
NP-345 (120/240 generator Sears)	2.60	5	13.00
NP-302 (air pump - Welden)	1.85	5	9.25
NP-271 (Cent. Pump Homelite)	9.65	5	48.25
NP-279 (Cent. pump - C.H. & E)	9.65	5	48.25
Total Equipment Cost			<u>\$213.75</u>

TOTAL COST

\$683.88

APR 27 1981

INDUSTRIAL WASTE
MONITORING AND ANALYSES REPORT

Plant from MID-AM MILK DISCHARGE IN JORDAN CREEK SIC _____ Date 3/31/81 Time 2:00
Sampling point _____ Method GRAB
Set up by _____ Removed by CHANDLER Time _____
Flow _____ Meter Start _____ Meter Ending _____
Seal _____ Entered in billing file _____ by _____

Sample No.	Time	Meter Reading	Test	Date	Analyst	Result	#
1			BOD ₅			1.17	
2			Total SS			18	
3			pH			7.20	
4			Organic Carbon			—	
5			Total Carbon			145	
6			C.O.D.			174	
7			O-PO ₄ -P				
8			TP				
9			NH ₃ -N				
10			TKN				
11			Phenol				
12			Oil & Grease				
13			Nitrate				
14			Nitrite				
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							

PW099

800 W. TAMPA

CITY OF SPRINGFIELD
INTER-OFFICE MEMORANDUM

ATTENTION OF _____ FILE _____
DEPARTMENT _____

DATE November 20, 1980

On Wednesday, November 19, 1980, at 3:30 p.m. Randy Lyman, Steve Short, and I observed a milky white discharge in Jordan Creek. We traced the discharge to the storm sewer box at the intersection of Missouri and Wall that comes down from Mid-America Dairymen.

I talked to Larry Boyd, a foreman at Mid-Am, who had no knowledge of the discharge. I informed him that such a discharge is a violation of local, State and Federal Water Pollution Laws and suggested that he call the Missouri Department of Natural Resources to inform them of the discharge.

KC:js

cc: Greg Perkins, Missouri Department of Natural Resources

800 W. TAMPA

SIGNED

RAB

November 20, 1980

Mr. Larry Boyd
Mid-America Dairymen, Inc.
800 W. Tampa
Springfield, Missouri 65802

Dear Mr. Boyd:

On Wednesday, November 19, 1980, at approximately 3:30 p.m. personnel from the City's Water Pollution Control Section observed a milky white discharge in the storm sewer box at the intersection of Missouri and Wall that comes down from Mid-America Dairymen, Inc.

Please be advised that a discharge of wastewater as noted above is in violation of City, State and Federal Water Pollution Control Laws. This office advises you to dispose of such waste in a proper waste treatment system.

If this office can be of service to you in answering any questions, please do not hesitate to call.

Yours truly,

Karen A. Chandler
Water Pollution Control Inspector II
Surveillance and Enforcement

KAC:js

cc: Greg Perkins, Missouri Department of Natural Resources
Robert R. Schaefer, P.E., Superintendent of Sanitary Services

800 W. TAMPA

CITY OF SPRINGFIELD
INTER-OFFICE MEMORANDUM

ATTENTION OF _____ FILE _____

DATE January 6, 1980

DEPARTMENT _____

On Friday, January 2, 1981, at 3:00 p.m., Gene Pabst and J. D. Slaughter observed a milky discharge in the Jordan Creek. They traced the discharge to the storm sewer below Mid-America Dairymen and called Bob Corson and me about the spill. We contacted Larry Boyd of Mid-Am. He knew nothing about the spill. Upon investigation, it appeared that the sanitary sewer in the receiving area had a stoppage causing milk to flow out of the area into a nearby storm sewer. We advised Larry Boyd to report the spill to the Missouri Department of Natural Resources. The milk in the creek had become too diluted to pump it into the sanitary sewer by the time this Department discovered it.

Karen Chandler

Karen A. Chandler
Water Pollution Control Inspector II
Surveillance & Enforcement

KAC:js

cc: Robert Schaefer, P.E. City of Springfield
Ed Sears, Missouri Department of Natural Resources

SIGNED _____

800 cc. Tampa